

Calibrating your Pipe Site

DISCLAIMER: Laser performance may vary slightly due to environmental factors. Expect reasonable accuracy.

Calibration Instructions:

- Use a plumb laser to mark the center point.
- Choose one set screw and use the provided Allen key to adjust it until the laser dot aligns with the center mark.
- If needed, repeat with the second set screw.
- Rotate the Pipe Site on the conduit to check alignment.
- Make further adjustments as necessary.

Scan QR Code for video instructions:

